

**SGS ITALIA S.p.A.**  
**ORGANISMO NOTIFICATO N. 1381**

Industrial  
 Via Caldera, 21  
 20153 Milano  
 Tel. (02) 7393.1 Fax: (02) 70125067  
 Affiliate code 095103

Id. : CER.CPR. Strutture acciaio e Alluminio  
 Rev. 1  
 Page 1 of 1

**Certificato di Conformità del Controllo della Produzione in Fabbrica**  
**1381-CPR-238 Venezia, 09 Maggio 2019**

In conformità al Regolamento 305/2011/EU del Parlamento Europeo e del Consiglio del 9 Marzo 2011 (Regolamento dei Prodotti da Costruzione o CPR), questo certificato si applica al prodotto da costruzione

**Elementi strutturali in acciaio**

*Fabbricato da*

Fabbricante e sua qualifica: **SCANDIUZZI STEEL CONSTRUCTIONS S.P.A.**

Indirizzo: **Via Piave, 14 – 31040 – Volpago del Montello (TV)**

Questo certificato attesta che tutte le disposizioni riguardanti la valutazione e la verifica della costanza della prestazione descritte nell' allegato ZA delle norme

**EN 1090-1:2009+A1:2011 Esecuzione di Strutture di Acciaio**  
**in classe di esecuzione fino a EXC4 secondo UNI EN 1090-2**  
**in accordo alla norma UNI EN ISO 3834-2**

Nell'ambito del sistema 2+ sono state applicate e che  
**Il controllo della produzione in fabbrica soddisfa tutti i requisiti prescritti di cui sopra.**

Questo certificato è stato emesso la prima volta il **09 Maggio 2019** e ha validità sino a che i metodi di prova e/o i requisiti del controllo della produzione in fabbrica stabiliti nelle norme armonizzate ( di cui sopra), utilizzati per valutare la prestazione delle caratteristiche dichiarate, non cambino, e il prodotto e le condizioni di produzione nello stabilimento non subiscano modifiche significative.

NOTA: Questo certificato sostituisce il certificato N. **1381-CPR-238**, emesso per la prima volta in data 11 Marzo 2014.

Data ultima emissione: **09 Maggio 2019**

Il Rappresentante Autorizzato  
 p.p. Marco De Maria

Il Direttore Tecnico  
 Flaviano Prosperi-Flaviani

Member of SGS (Société Générale de Surveillance) Group



Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test/laboratory results, reports or certifications. Any holder of this document is advised that the information contained hereon is limited to visual examination of the safely and readily accessible portions of the consignment only. Solely for services related to witnessing/observing a third party's intervention(s), in accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.